

Title	Radioactive Materials Collection and Transport
Specimen Requirements	<p>Samples for radioactive material testing must be submitted by a County Health Department, a State Agency, or a Federal Agency.</p> <p>Contact Jane Smith: 317-921-5515 or Rex Bowser: 317-351-7190 ex. 257 for further instructions.</p>
Sampling Materials	Sampling materials can vary widely depending upon the material that is to be sampled.
Procedural Notes	<p>Wipe Samples from Lead Paint Analyzers: With 2 small plastic bags, sharpie marker, Lead Painter Analyzer and alcohol wipes to be used to obtain the sample, place an unused alcohol wipe in one of the plastic bags and mark the bag "Blank Wipe".</p> <p>The following information and an individual plastic bag for each Analyzer to be wiped is required: Location: Your County Health Dept. with contact information Manufacture and model of the analyzer: Analyzer Unit Serial number: Source Isotope: Source Date: Source Activity on that date:</p> <p>Water Samples: The volume required can vary and glass or plastic may be required for sample integrity to be maintained. Contact Jane Smith at 317-921-5515 and the proper sample container will be shipped to your facility.</p> <p>Unknowns Samples: Contact Jane Smith: 317-621-5515 or Rex Bowser: 317-351-7190 ex. 257 for further instructions.</p>
Shipping Instructions	<p>Place sample(s) in an appropriate shipping container and ship or deliver to:</p> <p>ISDH Laboratories Radiochemistry Laboratory 550 W. 16th Street, Suite B Indianapolis, IN 46202</p>
Reporting and TAT	